

APPENDIX C: ACOUSTIC ASSESSMENT SUMMARY TABLE

Nalco Canada 1055 Truman Street, Burlington, ON
Acoustic Assessment Summary Table – Regular Operation

POR ID	POR Description	Sound Level at Point of Reception (day evening/night, Leq-1 hr, dBA)	Verified by Acoustical Audit (Y/N)	Performance Limit * (day/night, Leq-1 hr dBA)	Compliance with Performance Limit (Y/N)
POR01	Bungalow house at 2077 Churchill Avenue	49/47	N	57/54	Y
POR02	Two storey house at 2075 Churchill Avenue	52/51	N	57/54	Y
POR03	Two storey house at 2073 Churchill Avenue	51/50	N	57/54	Y
POR04	Raised bungalow house at 2076 Churchill Avenue	49/48	N	57/54	Y
POR05	Two storey house at 2074 Churchill Avenue	49/49	N	57/54	Y
POR06	Two storey house at 2072 Churchill Avenue	49/48	N	57/54	Y
POR07	Raised bungalow house at 2081 Leighland Road	53/52	N	57/54	Y
POR08	Two storey house at 2079 Leighland Road	48/46	N	57/54	Y
POR09	Two storey house at 2077 Leighland Road	50/49	N	57/54	Y
OPOR01	Outdoor area of POR01	49	N	57	Y
OPOR02	Outdoor area of POR02	49	N	57	Y
OPOR03	Outdoor area of POR03	49	N	57	Y
OPOR04	Outdoor area of POR04	48	N	57	Y
OPOR05	Outdoor area of POR05	48	N	57	Y
OPOR06	Outdoor area of POR06	47	N	57	Y
OPOR07	Outdoor area of POR07	47	N	57	Y
OPOR08	Outdoor area of POR08	49	N	57	Y
OPOR09	Outdoor area of POR09	49	N	57	Y

* Performance limit is based on the ambient noise level mentoring results for the facility addressed in the AAR.